

ROUTER



ROUTER TRAINING TUTORIAL

To order more books:

Call 1-800-529-5517 or

Visit www.emastercam.com or

Contact your Mastercam dealer



HOW TO DOWNLOAD:

Mastercam Home Learning Edition (HLE) Demo Software

Visit www.eMastercam.com/files

Click on Mastercam Demo Software from the categories on the right.

Proceed to download!

Mastercam 2020 Router Training Tutorial

Copyright: 1998 - 2019 In-House Solutions Inc. All rights reserved

Software: Mastercam 2020

Authors: Mariana Lendel

ISBN: 978-1-77146-839-8

Date: August 26, 2019

Notice

In-House Solutions Inc. reserves the right to make improvements to this manual at any time and without notice.

Disclaimer Of All Warranties And Liability

In-House Solutions Inc. makes no warranties, either express or implied, with respect to this manual or with respect to the software described in this manual, its quality, performance, merchantability, or fitness for any particular purpose. In-House Solutions Inc. manual is sold or licensed "as is." The entire risk as to its quality and performance is with the buyer. Should the manual prove defective following its purchase, the buyer (and not In-House Solutions Inc., its distributer, or its retailer) assumes the entire cost of all necessary servicing, repair, of correction and any incidental or consequential damages. In no event will In-House Solutions Inc. be liable for direct, indirect, or consequential damages resulting from any defect in the manual, even if In-House Solutions Inc. has been advised of the possibility of such damages. Some jurisdictions do not allow the exclusion or limitation of implied warranties or liability for incidental or consequential damages, so the above limitation or exclusion may not apply to you.

Copyrights

This manual is protected under International copyright laws. All rights are reserved. This document may not, in whole or part, be copied, photographed, reproduced, translated or reduced to any electronic medium or machine readable form without prior consent, in writing, from In-House Solutions Inc.

Trademarks

Mastercam is a registered trademark of CNC Software, Inc.

Microsoft, the Microsoft logo, are registered trademarks of Microsoft Corporation;

Windows 10 is a registered trademarks of Microsoft Corporation.

Table Of Contents

| Router Projects | |
|--|----|
| Getting Started | |
| Objectives | 18 |
| Step 1: Starting Mastercam | |
| Step 2: GUI - Graphical User Interface | 19 |
| Step 3: Navigate Through Mastercam | |
| Step 4: Set The Attributes | |
| Step 5: Manager Panels | 24 |
| Step 6: Setting Mastercam To Imperial | 26 |
| Step 7: Set The Grid | |
| Conventions Used In This Book: | 29 |
| Mastercam [®] Work Flow | |
| Tutorial 1: Geometry Creation | |
| | |
| Overview Of Steps Taken To Create The Part Geometry: | 34 |
| Overview Of Steps Taken To Create The Part Geometry: | |
| Overview Of Steps Taken To Create The Part Geometry: GEOMETRY CREATION Step 1: Setting Up The Graphic User Interface | |
| Overview Of Steps Taken To Create The Part Geometry: GEOMETRY CREATION Step 1: Setting Up The Graphic User Interface Step 2: Set The Default Machine To Inch | |
| Overview Of Steps Taken To Create The Part Geometry: GEOMETRY CREATION Step 1: Setting Up The Graphic User Interface Step 2: Set The Default Machine To Inch Step 3: Create Construction Lines | |
| Overview Of Steps Taken To Create The Part Geometry: GEOMETRY CREATION Step 1: Setting Up The Graphic User Interface Step 2: Set The Default Machine To Inch Step 3: Create Construction Lines Step 4: Create A Perpendicular Line | |
| Overview Of Steps Taken To Create The Part Geometry: GEOMETRY CREATION Step 1: Setting Up The Graphic User Interface Step 2: Set The Default Machine To Inch Step 3: Create Construction Lines Step 4: Create A Perpendicular Line Step 5: Create Parallel Lines | |
| Overview Of Steps Taken To Create The Part Geometry:GEOMETRY CREATIONStep 1: Setting Up The Graphic User InterfaceStep 2: Set The Default Machine To InchStep 3: Create Construction LinesStep 4: Create A Perpendicular LineStep 5: Create Parallel LinesStep 6: Create A Polar Line | |
| Overview Of Steps Taken To Create The Part Geometry:GEOMETRY CREATIONStep 1: Setting Up The Graphic User InterfaceStep 2: Set The Default Machine To InchStep 3: Create Construction LinesStep 4: Create A Perpendicular LineStep 5: Create Parallel LinesStep 6: Create A Polar LineStep 7: Trim The Entities | |
| Overview Of Steps Taken To Create The Part Geometry:GEOMETRY CREATIONStep 1: Setting Up The Graphic User InterfaceStep 2: Set The Default Machine To InchStep 3: Create Construction LinesStep 4: Create A Perpendicular LineStep 5: Create Parallel LinesStep 6: Create A Polar LineStep 7: Trim The EntitiesStep 8: Create A Line Knowing The Endpoints | |
| Overview Of Steps Taken To Create The Part Geometry:GEOMETRY CREATIONStep 1: Setting Up The Graphic User InterfaceStep 2: Set The Default Machine To InchStep 3: Create Construction LinesStep 4: Create A Perpendicular LineStep 5: Create Parallel LinesStep 6: Create A Polar LineStep 7: Trim The EntitiesStep 8: Create A Line Knowing The EndpointsStep 9: Create A 1/4" Fillet | |
| Overview Of Steps Taken To Create The Part Geometry: GEOMETRY CREATION Step 1: Setting Up The Graphic User Interface Step 2: Set The Default Machine To Inch Step 3: Create Construction Lines Step 4: Create A Perpendicular Line Step 5: Create Parallel Lines Step 6: Create A Polar Line Step 7: Trim The Entities Step 8: Create A Line Knowing The Endpoints Step 9: Create A 1/4" Fillet Step 10: Transform Mirror | |



| 69 |
|-----|
| 71 |
| 74 |
| 76 |
| 78 |
| 80 |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| 134 |
| |
| 137 |
| |



| Setup Sheet: | 137 |
|---|-----|
| Step 7: Select The Machine And Setup The Stock | |
| Step 8: Contour Toolpath | 142 |
| Step 9: Backplot The Toolpaths | |
| Step 10: Simulate The Toolpath In Verify | |
| Step 11: Move The Lead In/out | |
| Step 12: Post The File | 159 |
| Step 13: Save The Updated MCAM File | |
| Review Exercise - Student Practice | |
| Create The Geometry For Tutorial #2 Exercise | |
| Create The Toolpaths For Tutorial #2 Exercise | |
| Tutorial #2 Quiz | |
| Tutorial 3 | |
| GEOMETRY CREATION | |
| Step 1: Setting Up The Graphic User Interface | |
| Step 2: Create A Rectangle | |
| Step 3: Create Parallel Lines | |
| Step 4: Create 1/4" Holes For The Fixed Shelves | |
| Step 5: Create The Holes For The Moving Shelf | |
| Step 6: Translate The Holes | |
| Step 7: Trim The Lines For The Cut Out | |
| Step 8: Delete The Construction Lines | |
| Step 9: Save The File | |
| Toolpath Creation | |
| Setup Sheet: | |
| Step 10: Select The Machine And Setup The Stock | |
| Step 11: Drill The Through Holes | |



| Step 12: Backplot The Toolpaths | |
|--|--|
| Step 13: Simulate The Toolpath In Verify | |
| Step 14: Block Drill The Holes For The Moving Shelf | |
| Step 15: Cut The Knock Out | |
| Step 16: Cut The Relief For The Backboard | |
| Step 17: Post The File | |
| Step 18: Save The Updated MCAM File | |
| Review Exercise - Student Practice | |
| Create The Geometry For Tutorial #3 Exercise | |
| Create The Toolpaths For Tutorial #3 Exercise | |
| Tutorial #3 Quiz | |
| Tutorial 4 | |
| Overview Of Steps Taken To Create The Final Part: | |
| Geometry Creation | |
| Step 1: Setting Up The Graphic User Interface | |
| Step 2: Create A Door | |
| Step 3: Translate The Geometry | |
| Step 4: Change The Graphic View And Construction Plane | |
| Step 5: Create Parallel Lines | |
| Step 6: Create Two Rectangles | |
| Step 7: Delete The Construction Lines | |
| Step 8: Create Arcs For The Hinges | |
| Step 9: Create The Striker | |
| Step 10: Create The Striker Holes | |
| Step 11: Save The File | |
| Toolpath Creation | |
| Setup Sheet | |
| Step 12: Select The Machine And Setup The Stock | |



| | Step 13: Pocket The Inside Profiles | 268 |
|---|---|-----|
| | Step 14: Backplot The Toolpaths | 276 |
| | Step 15: Simulate The Toolpath In Verify | 277 |
| | Step 16: Chamfer The Pocket Walls | 279 |
| | Step 17: Change The Plane To The Left | 284 |
| | Step 18: Machine The Two Hinge Mortises | 285 |
| | Step 19: Drill The Hinge Holes | 290 |
| | Step 20: Change The Plane To The Right Side | 296 |
| | Step 21: Machine The Striker Mortise | 297 |
| | Step 22: Drill The Striker Holes | 302 |
| | Step 23: Circle Mill The Striker Hole | 310 |
| | Step 24: Post The File | 317 |
| | Step 25: Save The Updated Mcam File | 318 |
| | Review Exercise - Student Practice | 319 |
| | Create The Geometry For Tutorial #4 Exercise | 320 |
| | Create The Toolpaths For Tutorial #4 Exercise | 321 |
| | Tutorial #4 Quiz | 326 |
| Т | utorial 5 | 327 |
| | Overview Of Steps Taken To Create The Final Part: | 328 |
| | GEOMETRY CREATION | 330 |
| | Step 1: Setting Up The Graphic User Interface | 330 |
| | Step 2: Open Tutorial #1 Geometry | 330 |
| | Step 3: Merge Tutorial #2 Geometry | 332 |
| | Step 4: Change The Wireframe Color | 334 |
| | Step 5: Option #1 | 335 |
| | Arrange Tutorials 1 & 2 Parts Using Rectangular Nesting | 335 |
| | Step 6: Save The File | 343 |



| | Toolpath Creation | 344 |
|---|---|-------|
| | Setup Sheet | 344 |
| | Step 7: Select The Machine And Setup The Stock | 345 |
| | Step 8: Drill The 1/2" Holes | 349 |
| | Step 9: Backplot The Toolpaths | 357 |
| | Step 10: Simulate The Toolpath In Verify | 358 |
| | Step 11: Change The Color Of The 1/2" Arcs | 360 |
| | Step 12: Contour The Parts | 362 |
| | Step 13: Post The File | . 372 |
| | Step 14: Save The Updated MCAm File | . 374 |
| | Option #2 | 375 |
| | Step 15: Trueshape Nesting | 375 |
| | Step 16: Save The File | 384 |
| | Option #3 | 385 |
| | Step 17: Rectangular Nesting The Toolpaths | 385 |
| | Toolpath Creation | 386 |
| | Step 18: Translate The Geometry | 386 |
| | Step 19: Contour The First Part | 390 |
| | Step 20: Contour The Second Part | 398 |
| | Step 21: Rectangular Nesting The Toolpaths | 401 |
| | Step 22: Post The File | . 409 |
| | Step 23: Save The Updated MCAM File | 409 |
| | Review Exercise - Student Practice | 410 |
| | Create The Geometry For Tutorial #5 Exercise | . 411 |
| | Create The Toolpaths For Tutorial #5 Exercise | 412 |
| | Tutorial #5 Quiz | 415 |
| т | utorial 6 | . 417 |
| | Overview Of Steps Taken To Create The Final Part: | . 418 |



| GEOMETRY CREATION | 420 |
|--|-----|
| Step 1: Setting Up The Graphic User Interface | 420 |
| Step 2: Download The File | |
| Step 3: Use Raster To Vector To Open The File | |
| Step 4: Create A Point | |
| Step 5: Create Text | 429 |
| Step 6: Create More Text | 434 |
| Step 7: Remove The Point | 437 |
| Step 8: Create A Rectangle Around The Graphics | 437 |
| Step 9: Move The Origin | 439 |
| Step 10: Save The File | 440 |
| Toolpath Creation | |
| Setup Sheet | 441 |
| Step 11: Select The Machine And Setup The Stock | 442 |
| Step 12: Machine The Helmet Using Contour Toolpath | |
| Step 13: Backplot The Toolpaths | 455 |
| Step 14: Simulate The Toolpath In Verify | 456 |
| Step 15: Engrave The Letters | |
| Step 16: Post The File | 467 |
| Step 17: Save The Updated MCAM File | 468 |
| Review Exercise - Student Practice | |
| Create The Geometry For Tutorial #6 Exercise | 470 |
| Create The Toolpaths For Tutorial #6 Exercise | 470 |
| Tutorial #6 Quiz | |
| Tutorial 7 | |
| Overview Of Steps Taken To Create The Final Part: | 476 |
| GEOMETRY CREATION | 478 |



| Step 1: Setting Up The Graphic User Interface | |
|---|-----|
| Step 2: Create A Rectangle | 478 |
| Step 3: Create Parallel Lines | |
| Step 4: Create Fillets | 483 |
| Step 5: Create The Slots In The Desk | |
| Step 6: Save The File | 491 |
| Step 7: Create A Custom Tool | 491 |
| Step 8: Create A Rectangle | |
| Step 9: Create Parallel Lines | |
| Step 10: Trim Entities | 496 |
| Step 11: Create An Arc | |
| Step 12: Delete The Construction Lines | |
| Step 13: Trim Divide/delete | 501 |
| Step 14: Change The Line Style | |
| Step 15: Save The Tool Geometry | 504 |
| Toolpath Creation | 505 |
| Setup Sheet | |
| Step 16: Open The Desk Geometry | 506 |
| Step 17: Select The Machine And Setup The Stock | |
| Step 18: Slot Mill | 511 |
| Step 19: Backplot The Toolpaths | |
| Step 20: Simulate The Toolpath In Verify | |
| Step 21: Cut The Desk Profile | 524 |
| Step 22: Post The File | |
| Step 23: Save The Updated MCAM File | |
| Review Exercise - Student Practice | 539 |
| Create The Geometry For Tutorial #7 Exercise | |
| Create The Toolpaths For Tutorial #7 Exercise | |



| Tutorial #7 Quiz | |
|---|-----|
| Tutorial 8 | |
| Overview Of Steps Taken To Create The Final Part: | |
| GEOMETRY CREATION | |
| Step 1: Setting Up The Graphic User Interface | |
| Step 2: Download The File | |
| Step 3: Open The File | |
| Step 4: Save The File | |
| Toolpath Creation | |
| Setup Sheet | |
| Step 5: Select The Machine And Setup The Stock | |
| Step 6: Circle Mill The Center Pocket | |
| Step 7: Backplot The Toolpaths | |
| Step 8: Simulate The Toolpath In Verify | |
| Step 9: Drill The Hole | |
| Step 10: Engrave The Numbers | |
| Step 11: Contour Ramp The Slots | |
| Step 12: Pocket Toolpath | |
| Step 13: Cut The Through Pockets | |
| Step 14: Contour The Outside Of The Clock | |
| Step 15: Post The File | 613 |
| Step 16: Save The Updated MCAM File | 614 |
| Review Exercise - Student Practice | 615 |
| Create The Geometry For Tutorial #8 Exercise. | 616 |
| Create The Toolpaths For Tutorial #8 Exercise | 616 |
| Tutorial #8 Quiz | |
| Quiz Answers | |





Router Projects



Router

| Tutorial | Geometry Functions | Toolpath Creation |
|----------|---|---|
| #1 | Create Polar Line. Create Perpindicular Line. Create Parallel Lines. Trim Entities. Create Fillets. Xform Mirror. Xform Translate. Create Circle Center Point. Create Rectangle. | Create a Drilling Toolpath. Create a Contour Toolpath. |
| #2 | | |
| | Create Lines. Create Fillets. Create Arcs. | Create a Contour Toolpath. |
| #3 | | |
| | Create Rectangle. Create Parallel Lines. Create Circle Center Point. Xform Rectangular Array. Trim Geometry. Delete Construction Lines. | Create a Drilling Toolpath. Create a Block Drilling Toolpath. Create a Contour Toolpath. |
| | Create Door. Xform Translate. Change Graphic View and Construction Plane. Create Parallel Lines. Create Rectangles. Delete Construction Lines. Create Circle Center Point. Create Rectangular Shapes. | Create a Pocket Toolpath. Create a Engraving Toolpath. Create Toolpaths on Left and Right Plane. Create Drilling Toolpaths. Create a Circle Mill Toolpath. |
| #5 | | |
| | Open Tutorial #1. Merge Tutorial #2. Xform Geometry Nesting. Option #2 (True Shape Nesting). Option #3 (Rectangular Nesting The Toolpaths). | Create Drill Toolpath. Create a Contour Toolpath. |



| Tutorial | Geometry Functions | Toolpath Creation |
|----------|---|--|
| #6 | Download the File. Use RAST2VEC.DLL to Open The File. Create a Point. Create Letters. | Create a Contour Toolpath. Create an Engraving Toolpath. |
| #7 | Create Rectangle. Create Line Parallel. Create Fillets. Create Rectangular Shapes. Create a Custom Tool. Trim Entities. Create Arc Endpoints. Delete Construction Lines. | Create a Slot Mill Toolpath. Create Contour Toolpath Using The Custom Tool Created. |
| #8 | Download the File. | Create a Circle Mill Toolpath. Create a Drilling Toolpath. Create a Engraving Toolpath. Create a Contour (Ramp) Toolpath. Create a Pocket Toolpath. |



Tutorial 4





Router

OVERVIEW OF STEPS TAKEN TO CREATE THE FINAL PART:

From Drawing to CAD Model:

- The student should examine the drawing on the following page to understand what part is being created in the tutorial.
- From the drawing we can decide how to go about creating the geometry in Mastercam.

Create the CAD Model used to generate Toolpaths from:

- The student will create the wireframe needed to create the surfaces.
- Create a door using the Door command.
- Create side holes.

Create the necessary Toolpaths to machine the part:

- The student will set up the stock size and the clamping method used.
- Machine the pockets using a straight bit.
- Machine the pocket walls using an engraver tool to create a chamfer.
- Drill the two side holes.
- Use an aggregate to mill the door jam.

Backplot and Verify the file:

- Backplot will be used to simulate a step by step process of the tool's movements.
- Verify will be used to watch a tool machine the part out of a solid model.

Post Process the file to generate the G-code:

• The student will then post process the file to obtain an NC file containing the necessary code for the machine.

This tutorial takes approximately one hour to complete.





GEOMETRY CREATION

STEP 1: SETTING UP THE GRAPHIC USER INTERFACE

Please refer to the Getting Started section to set up the graphics user interface.

STEP 2: CREATE A DOOR

In this step you will learn how to create a door using the **Create Door Geometry** command. This command automates the process so you are required to input only a few values to create a door.

Step Preview:



Wireframe

• From the **Router** group, select **Create Door Geometry** as shown.





• Select the Door style **Notched** and modify the door size and inside shape dimensions as shown.



• Select the OK button once the parameters have been changed to create the door.



• To place the lower left corner of the door select the **Origin** as shown.



- Press **Alt + F1** to view the geometry.
- Press **Esc** to finish the command.
- The geometry should look as shown.





STEP 3: TRANSLATE THE GEOMETRY

In this step you will translate the geometry to give the door a 3D appearance. This will help us when we create the holes for the hinges and striker holes.

Step Preview:



Transform

• From the **Position** group, select the **Translate** icon as shown.



• Hold down the **Shift** key and select the line as shown.

Note: Holding the *Shift* key allows you to select multiple entities that are touching each other creating a chain.





End Selection

- Once the entities are selected click on the End Selection button or press Enter.
- In the **Translate** dialog box enable **Join** and enter a **Delta Z** value of **-1.0** as shown.

| Translate | Ψ × |
|---|--|
| Basic Advanced | < <> <> <> <> <> <> <> <> <> <> <> <> <> |
| Entity Method: Ocopy Move I Join | ۲ |
| Selection Reselect | ۲ |
| Instances | ۲ |
| Number: 1 | \$ |
| Distance: Between Total | |
| Delta | ۲ |
| X: 0.0000 | - ‡ |
| Y: 0.0000 | - \$ |
| Z: -1.0000 | - ¢ |

- Select the OK button to exit the Translate panel.
- Right mouse click on the graphics window and select the **Clear Colors** button to reset the color to the system color.

| * | Ŧ | | _ | - | | * | ዊ | Ŧ | 0 | Ŧ | 臣 | - T | ٢ | - |
|---------|---|------|---|-----|---|---|----|----|-----|---|---|-----|---|---|
| | | -)3D | Ζ | 0.0 | • | 3 | 1: | In | ner | | • | Ľ | | |



STEP 4: CHANGE THE GRAPHIC VIEW AND CONSTRUCTION PLANE

You will change the Graphics view to Isometric to view the translation and change the Construction plane to the Right plane so we can create geometry on the right side of the door.

Step Preview:



• Select the Planes tab to open Planes Manager as shown.

| | | \frown | | | |
|-----------|--------|----------|--------|------------------|-----|
| Toolpaths | Solids | Planes | Levels | Recent Functions | Art |

• Set the **Construction plane** and the **Toolpath plane** to the **Right** as shown.

| Name | G | WCS | - | С | т | Offset |
|-------------------------------|---|-----|---|---|---|--------------|
| 🗸 Тор | | WC | s | | | |
| Trimetric | | | | _ | _ | |
| < Right | | | (| С | т | $\mathbf{)}$ |
| Left | | | | | | - |
| Isometric reverse | | | | | | |
| Isometric | G | | | | | |
| Front | | | | | | |
| Bottom | | | | | | |
| Back | | | | | | |
| | | | | | | |

Note: If you select the Isometric Graphics view at anytime while being in a different plane, the planes will be reset to Top.

• Press Alt + F1 to fit the geometry to the screen.

• The grid should look as shown.



STEP 5: CREATE PARALLEL LINES

You will create parallel lines in the right plane, knowing the offset direction and distance. These lines will be used to help us establish the side pocket locations.

Step Preview:





Wireframe

• From the Lines group, select Line Parallel as shown.

| File | Home | Wireframe Sur | faces Solids | Model Prep | Drafting | Transform |
|---------------------|---------------------|---|----------------------------|------------|---------------------------------|--------------------|
| Point Position * | + Bolt Circle | Line Part Line Line Pert Endpoints 1 Line Clo | rpendicular osest * Cen | Circle | Yoints ngent Edge Point ≠ | Spline Manual * |
| Poir | nts | Lines | | Arcs | | Splines |

• [Select a line]: Select Entity A as shown.



• [Select the point to place the parallel line through]: Select a point to the right of the selected line.

Note: The color of the line is cyan which means the entity is "live" and you can still change the entities parameters.



STEP 13: POCKET THE INSIDE PROFILES

Pocket toolpath is used to clean out material from an enclosed boundary. You will create a pocket toolpath to cut the inside profiles. This will give the door a 3D appearance.

Step Preview:



Toolpaths

• From the **2D** group, select **Pocket** as shown.

| File | Home | Wireframe | Surfaces | Solids | Model Prep | Drafting | Transform | Mach | ine | View | Toolpaths |
|---------|--------|--------------|--------------|-------------|------------|---------------|-----------------|-----------------|-------------|-------|--------------|
| Dynamic | C | ket Peel Mil | II Area Mill | , v T | OptiRough | Pocket | P roject | Parallel | * * * | Curve | Swarf Milli. |
| | \sim | 2D | | | | 3 | D | | | | 1 |

• Make sure that the **Chain** button is selected in the **Chaining** dialog box.





• Select the four chains in a CW direction and in the order shown.



Note: The arrows shown disappear as you select the next chain. They are showing you the chaining direction.

- Select the OK button to exit the Chaining dialog box.
- On the **Toolpath Type** page make sure that **Pocket** is selected.



13.1 Select a 3/8" Straight Bit from the library and set the tool parameters

- Select **Tool** from the **Tree view area**.
- Click on the Select library tool button.
 Select library tool...
- Then select the Filter button. Filter...



- Select the **None** button and then under **Tool Types** choose the **Flat Endmill** icon as shown.
- Under Tool Diameter, select Equal and enter the value 0.375.

| Tool List Fil | ter | | | | × |
|---------------|-----|----------------|-------------------|--|---|
| | s | All sking ~ | None Unit mask | | Tool Diameter Equal 0.375 Radius Type None Corner Material MSS Ceramic Carbide User Def 1 Ti Coated User Def 2 All None Copy job setup matl |
| Heset a | | | | | |

- Select the OK button to exit the Tool List Filter.
- In the **Tool Selection** dialog box you should only see a **3/8**" **Straight Bit**.

| | # | Assembly | Tool Name | Holder N | Dia. | Cor. r | Length | # Flut | Туре | Rad |
|---|-----|----------|------------------|----------|-------|--------|--------|--------|-------|------|
| 2 | 146 | | 3/8 STRAIGHT BIT | | 0.375 | 0.0 | 2.0 | | Strai | None |

- Select the **3/8**" **Straight Bit** in the **Tool Selection** page and then select the **OK** button to exit.
- Select the **OK** button to accept the **Tool Settings Modified** dialog box.

| Tool Settings Modified | × |
|---|-------------|
| Current Tool Settings Modified | |
| In order to conform to your current Machine Def / Control Def parameters, sor this tool's settings have been changed. Any values that have been changed meet these settings will be shown in italics. | ne of to |
| | |
| Turn off warning for session | ✓ |



 \checkmark

V

• Make all the necessary changes as shown.

| 2D Toolpaths - Pocket | × |
|---|---|
| 🕴 🔚 👪 🖻 🥗 | |
| | |
| Toolpath Type Tool Holder ⊖ Cut Parameters ⊖ Broughing ⊖ Eacl In/Out ⊘ Depth Cuts ⊘ Break Through | # A Tool Name Holder N Dia. Cor. r 1 - 3/8 STRAIGHT BIT - 0.375 0.0 Tool name: 3/8 STRAIGHT BIT - 0.375 0.0 Tool name: 3/8 STRAIGHT BIT - 1 - Head #: -1 1 Diameter offset: 1 |
| Linking Parameters Home / Ref. Points Arc Filter / Tolerance Planes (WCS) Coolant Canned Text Misc Values Quick View Settings Tool 3/8 STRAIGHT | RCTF Spindle direction: CW Feed rate: 200.0 Spindle speed: 78000 Right-click for options FPT: 0.005 SFM 1963.3508 |
| Tool Diameter 0.375 Comer Radius 0 Feed Bate 200 | Select library tool Filter Active Filter Filter Force tool change Rapid Retract |
| Spindle Speed 18000 Coolant Off Tool Length 3 Length Offset 1 Diameter Offset 1 Cplane / Tpla Top | Comment Pocket the door |
| Axis Combinat Default | |
| 🤣 = disabled | ✓ × € |



13.2 Set the Cut Parameters

- In the Tree view area, select Cut Parameters.
- Set the **Stock to leave on walls** to **0.25** and ensure the rest of the parameters appear as shown.





13.3 Set the Roughing Parameters

- Select **Roughing** in the **Tree view area**.
- Change the **Cutting method** to **Constant Overlap Spiral** as shown.

| 2D Toolpaths - Pocket | | × |
|---|--|-------|
| 🕴 📙 👪 🖻 | | |
| 1 | | |
| Toolpath Type → Tool Holder → Cut Parameters → Roughing → Entry Motion → Finishing ↓ Gead In/Out → Death Outs | Rough Cutting method: Constant Overlap Spiral Zigzag Zigzag Constant Overlap Spiral Parallel Spiral Parallel Spiral, Morph Spiral Clean Corners | |
| Break Through | Stepover percentage 75.0 Imimize tool burial Tolerance for remachining and constant overlap s | piral |
| Home / Ref. Points | Stepover distance 0.28125 Spiral inside to outside 5.0 % 0.01875 | |
| Arc Filter / Tolerance | Roughing angle 0.0 Display stock for constant overlap spiral | |
| Planes (WCS) Coolant Conned Text Misc Values | Trochoidal cuts: Off Imaterial only Entire pocket | |
| Tool 3/8 STRAIGHT Tool Diameter 0.375 Corner Radius 0 Feed Rate 200 | Loop radius | |
| Spindle Speed 18000 Coolant Off Tool Length 3 Length Offset 1 Diameter Offset 1 | Loop spacing 0.1 Corner smoothing radius 0.1 | |
| Cplane / Tpla Top Axis Combinat Default | | |
| ✓ = edited ⊘ = disabled | × × | ? |



13.4 Set the Entry Motion

- Select Entry Motion from the Tree view area.
- Set the **Entry Motion** to **Off** as shown.

| 2D Toolpaths - Pocket | | | | × |
|-----------------------|--------|---------|--------|---|
| 🎙 🔚 🌃 🖻 🎽 | | | | |
| Toolpath Type | () Off | () Ramp | OHelix | |

13.5 Set the Finishing Parameters

• Select **Finishing** and disable **Finish** as shown.

| 2D Toolpaths - Pocket | | | | × |
|---|--------------------------|---|---|---|
| 🕴 🔚 🔣 🖻 | | | | |
| Toolpath Type ✓ Tool Holder Holder ✓ Cut Parameters ✓ Cut Parameters ✓ Entry Motion ✓ Lack In/Out Ø Depth Cuts Ø Break Through Linking Parameters Home / Ref. Points Arc Filter / Tolerance Planes (WCS) Coolant Canned Text Misr Values Ouick View Settings Tool 3/8 STRAIGHT Tool Diameter 0.375 Corner Radius Feed Rate 200 Spindle Speed 18000 Coolant Off Tool Length 1 Diameter Offset 1 Diameter Off | Finish Passes Spacing Sp | Cutter compensation Computer Optimize cutter comp in control Machine finish passes only at final depth Machine finish passes after roughing all p 2 2 2 7 fir 0.0 | Override Feed Speed 200.0 Feed rate 200.0 Spindle speed 18000 boockets 18000 mish passes per gh depth cut Max calculated finish step Max rough stepdown rom Depth Cuts Image: Spin Spin Spin Spin Spin Spin Spin Spin | |
| ✓ = edited⊘ = disabled | | | × × • | 2 |

13.6 Set the Linking Parameters

- Select Linking Parameters from the Tree view area.
- Set the Linking Parameters as shown.



• Select the **OK** button to generate the toolpath.



STEP 14: BACKPLOT THE TOOLPATHS

Backplotting shows the path the tools take to cut the part. This display lets you spot errors in the program before you machine the part. As you backplot toolpaths, Mastercam displays additional information such as the X, Y, and Z coordinates, the path length, the minimum and maximum coordinates, and the cycle time. It also shows any collisions between the workpiece and the tool.

Make sure that the toolpath is selected (signified by the green check mark on the folder icon). If the operation
is not selected choose the Select all operations icon.

| Toolpaths | ▼ ₽ × |
|-------------------------------------|------------------|
| 💽 🍾 The Tx 👫 - 🗟 🎭 🚟 G1 The | % |
| 6 ≈ 1 ▼ ▲ ⊑ ♦ ≈ 0 ⊡ • | X 9/ |

• Select the **Backplot selected operations** button.

| Toolpa | aths | | - | д | × |
|-------------------------------|-------|-----------------------|----|---|---|
| ▶ _k × _k | ī⊳ ī× | 🎼 - 🔕 🎭 📷 G1 🖬 🏏 | ?) | | |
| $\mathbf{B} \approx$ | ₩ . | ▲ ⊑ 🍝 🕅 🍕 🗗 💽 • 🛛 🛣 🌖 | | | |

• Right mouse click in the graphics window and select **Isometric**.

×

| \odot | Zoom Target |
|---------|---------------------------|
| Q | Zoom Window |
| ₽ | Unzoom 80% |
| 3 | Dynamic Rotation |
| Ħ | Fit |
| | Top (WCS) |
| ¢ | Front (WCS) |
| () | Right (WCS) |
| T | Isometric (WCS) |
| | GView |
| × | Delete Entities |
| ? | Analyze Distance |
| >? | Analyze Entity Properties |

- To fit the workpiece to the screen, if needed, right mouse click in the graphics window again and select Fit.
- You can step through the Backplot by using the Step forward box or Step back buttons.
- You can adjust the speed of the backplot.





• The toolpath should look as shown.



STEP 15: SIMULATE THE TOOLPATH IN VERIFY

Verify Mode shows the path the tools take to cut the part with material removal. This display lets you spot errors in the program before you machine the part. As you verify toolpaths, Mastercam displays additional information such as the X, Y, and Z coordinates, the path length, the minimum and maximum coordinates, and the cycle time. It also shows any collisions between the workpiece and the tool.

• From the Toolpaths Manager, select Verify selected operations icon as shown.



Note: Mastercam launches a new window that allows you to check the part using *Verify*.

• Change the settings for **Visibility** as shown.



• Select the Play (R) button to run Verify.

• The part should look as shown.



Note: To rotate the part, move the cursor to the center of the part and click and hold the mouse wheel and slowly move it in one direction.

To **Zoom In** or **Out** hold down the mouse wheel and scroll up or down as needed.

• To go back to Mastercam window, minimize Mastercam Simulator window as shown.



×