

Mastercam® 2020

IMPERIAL | TRAINING TUTORIAL SERIES

HLE
DOWNLOAD
INSTRUCTIONS INSIDE



2020



MULTIAXIS ESSENTIALS

Mastercam® 2020

MULTIAXIS ESSENTIALS TRAINING TUTORIAL

To order more books:

Call 1-800-529-5517 or

Visit www.emastercam.com or

Contact your Mastercam dealer



HOW TO DOWNLOAD:

Mastercam Home Learning Edition (HLE)
Demo Software

Visit www.eMastercam.com/files

Click on Mastercam Demo Software
from the categories on the right.

Proceed to download!

Mastercam 2020 Multiaxis Essentials Training Tutorial

Copyright: 1998 - 2020 In-House Solutions Inc. All rights reserved

Software: Mastercam 2020

Authors: Mariana Lendel

ISBN: 978-1-77146-841-1

Date: August 21, 2019

Notice

In-House Solutions Inc. reserves the right to make improvements to this manual at any time and without notice.

Disclaimer Of All Warranties And Liability

In-House Solutions Inc. makes no warranties, either express or implied, with respect to this manual or with respect to the software described in this manual, its quality, performance, merchantability, or fitness for any particular purpose. In-House Solutions Inc. manual is sold or licensed "as is." The entire risk as to its quality and performance is with the buyer. Should the manual prove defective following its purchase, the buyer (and not In-House Solutions Inc., its distributor, or its retailer) assumes the entire cost of all necessary servicing, repair, of correction and any incidental or consequential damages. In no event will In-House Solutions Inc. be liable for direct, indirect, or consequential damages resulting from any defect in the manual, even if In-House Solutions Inc. has been advised of the possibility of such damages. Some jurisdictions do not allow the exclusion or limitation of implied warranties or liability for incidental or consequential damages, so the above limitation or exclusion may not apply to you.

Copyrights

This manual is protected under International copyright laws. All rights are reserved. This document may not, in whole or part, be copied, photographed, reproduced, translated or reduced to any electronic medium or machine readable form without prior consent, in writing, from In-House Solutions Inc.




Trademarks




Mastercam is a registered trademark of CNC Software, Inc.




Microsoft, the Microsoft logo, are registered trademarks of Microsoft Corporation;

Windows 10 is a registered trademarks of Microsoft Corporation.

Multiaxis Essentials Projects

Tutorial	Toolpath Creation
<p>#1</p> 	<p>Contour With Axis Substitution.</p>
<p>#2</p> 	<p>Drilling With Axis Substitution. Drilling with Rotatry Axis Positioning. Contour With Axis Substitution. Transform Rotate.</p>
<p>#3</p> 	<p>Contour With Axis Substitution. Contour Indexing Using Planes.</p>

Tutorial	Toolpath Creation
<p>#4</p> 	<p>Rotary 4-Axis.</p>
<p>#5</p> 	<p>Curve 5 -Axis.</p>
<p>#6</p> 	<p>Swarf 5-Axis.</p>

Tutorial	Toolpath Creation
<p>#7</p> 	<p>Drill 5-Axis. Circle Mill 5-Axis.</p>
<p>#8</p> 	<p>Flow 5-Axis.</p>
<p>#9</p> 	<p>Multisurface 5-Axis</p>


Tutorial	Toolpath Creation
 <p>#7</p>	<p>Debur</p>

Table Of Content

Multiaxis Essentials Projects	3
Getting Started	15
Objectives	16
Step 1: Starting Mastercam	16
Step 2: GUI - Graphical User Interface	17
Step 3: Navigate Through Mastercam	18
Step 4: Set The Attributes	21
Step 5: Manager Panels	23
Step 6: Setting Mastercam To Imperial	25
Step 7: Set The Grid	27
Tutorial 1	29
Step 1: Create The Geometry Of The Cylindrical Helix	31
Step 2: Select The Machine And Set Up The Stock	39
Step 3: Machine The Cylindrical Helix - Axis Substitution About Y Axis	44
Step 4: Backplot The Toolpaths	54
Step 5: Verify The Toolpath	56
Step 6: Post The File To Generate The NC Code (Use A Different Machine)	58
Step 7: Save The Updated MCAM File	59
Step 8: Create The Geometry Of The Conical Helix	60
Step 9: Machine The Conical Helix - Axis Substitution About Y Axis	63
Step 10: Save The Updated MCAM File	65
Tutorial #1 Quiz	67
Tutorial 2	69
Step 1: Select The Geometry File	71
Step 2: Select The Machine And Set Up The Stock	72
Step 3: Drilling Toolpath- Axis Substitution About Y Axis	76


Step 4: Backplot The Toolpath	83
Step 5: Verify The Toolpath	85
Step 6: Drill The 8 Holes Using Axis Substitution Toolpath	86
Step 7: Axis Substitution About Y Axis - Contour Toolpath	93
Step 8: Machine The Top Slot - Contour Toolpath	103
Step 9: Transform-Rotate The Contour Toolpath About The Origin	111
Step 10: Post The File To Generate The NC Code	116
Tutorial #2 Quiz	120
Tutorial 3	121
Step 1: Select The Geometry File	123
Step 2: Select The Machine And Set Up The Stock	124
Step 3: Axis Substitution About Y Axis - Contour Toolpath	129
Step 4: Backplot The Toolpath	138
Step 5: Verify The Toolpath	141
Step 6: Define A New Tool Plane To Drill The Hole	143
Step 7: Drill The Hole In The New Plane	148
Step 8: Transform - Rotate To Machine The Rest Of The Holes	153
Step 9: Machine The Top Slot In The Top Tool Plane	159
Step 10: Machine The Bigger Slot In A New Tool Plane	168
Step 11: Post The File To Generate The NC Code	178
Step 12: Save The Updated MCAM File	179
Tutorial #4 Quiz	181
Tutorial 4	183
Step 1: Select The Geometry File	185
Step 2: Select The Machine And Set Up The Stock	186
Step 3: Rotary 4-Axis With Rotary Cut	191
Step 4: Rotary 4-Axis With Axial Cut	206
Step 5: Post The File To Generate The NC Code	219

Step 6: Save The Updated MCAM File	220
Tutorial #5 Quiz	222
Tutorial 5	223
Step 1: Select The Geometry File	225
Step 2: Select The Machine And Set Up The Stock	226
Step 3: Curve With Tool Axis Control Oriented To A Point	232
Step 4: Curve With Tool Axis Control Oriented From A Point	245
Step 5: Curve With Tool Axis Control Oriented Normal To A Plane	257
Step 6: Curve With Tool Axis Control Oriented Towards A Chain	268
Step 7: Curve With Tool Axis Control Oriented To Lines	277
Step 8: Post The File To Generate The NC Code	286
Step 9: Save The Updated MCAM File	287
Tutorial #5 Quiz	289
Tutorial 6	291
Step 1: Select The Geometry File	293
Step 2: Set Up The Stock	294
Step 3: Verify The Surface High Speed Toolpaths	299
Step 4: Create A Stock Model	300
Step 5: Swarf Toolpath With Walls Defined From The Chains	303
Step 6: Swarf Toolpath With Walls Defined From Surfaces	319
Step 7: Post The File To Generate The NC Code	327
Step 8: Save The Updated MCAM File	328
Tutorial #6 Quiz	330
Tutorial 7	331
Step 1: Select The Geometry File	333
Step 2: Select The Machine And Set Up The Stock	334
Step 3: Create The Smaller Hole Axes	339

Step 4: Spot Drill Toolpath	342
Step 5: Drill The Three 1/2" Diameter Holes	351
Step 6: Circle Mill Toolpath With Tool Axis Control	356
Step 7: Post The File To Generate The NC Code	366
Step 8: Save The Updated MCAM File	367
Tutorial #7 Quiz	369
Tutorial 8	371
Step 1: Select The Geometry File	373
Step 2: Select The Machine	374
Step 3: Flow 5 Axis Toolpath With Tool Axis Control Parallel To Lines	376
Step 4: Machine Simulation To Check The Flow 5 Axis	392
Step 5: Flow 5 Axis Toolpath With Tool Axis Oriented To A Point	399
Step 6: Transform - Rotate The Toolpath To Finish All Blades	413
Step 7: Post The File To Generate The NC Code	418
Step 8: Save The Updated MCAM File	419
Tutorial #9 Quiz	421
Tutorial 9	423
Step 1: Select The Geometry File	425
Step 2: Select The Machine	426
Step 3: Multisurface 5 Axis Toolpath To Rough The Cavity	429
Step 4: Machine Simulation To Check The Multisurface 5 Axis	444
Step 5: Multisurface 5 Axis Toolpath To Finish The Part	449
Step 6: Post The File To Generate The NC Code	461
Step 7: Save The Updated MCAM File	462
Tutorial #9 Quiz	464
Tutorial 10	465
Step 1: Select The Geometry File	467
Step 2: Select The Machine And Set Up The Stock	468

Step 3: 3 Axis Deburr Toolpath	472
Step 4: 3 + 2 Deburr Toolpath	484
Step 5: 5-Axis Deburr Toolpath	492
Step 6: Post The File To Generate The NC Code	499
Step 7: Save The Updated MCAM File	501
Tutorial #10 Quiz	503
Quiz Answers	505

Tutorial 4



OVERVIEW OF STEPS TAKEN TO CREATE THE FINAL PART:

Open the CAD Model:

- ◆ The student should examine the part file to understand what part is being created in the tutorial.

Create the necessary Toolpaths to machine the part:

- ◆ The student will set up the stock size to be used and the appropriate tool settings.
- ◆ The left and right side cams will be roughed using a Rotary 4-Axis toolpath with the axial cut method in a one way direction.
- ◆ The left and right side cams will then be finished using a Rotary 4-Axis toolpath with the rotary cutting method in a zig zag direction.

Backplot and Verify the file:

- ◆ The Backplot will be used to simulate a step-by-step process of the tool's movements.
- ◆ The Verify will be used to watch a tool machine the part out of a solid model.

Post Process the file to generate the G-code:

- ◆ The student will then post process the file to obtain an NC file containing the necessary code for the machine.

This tutorial takes approximately one hour to complete.

This tutorial covers Mastercam's 4 and 5-Axis toolpath functionality. To apply these toolpaths to a 5-Axis machine tool, a customized post processor for your machine is required.

There are no default 5-Axis post processors included with Mastercam due to the variation in multi-axis machine configurations. Contact your Mastercam reseller to request post processor services such as multi-axis post development.

Your post processor may require certain additional programming information not covered in this tutorial. For instance:

You may be required to position your stock in machine space rather than at Mastercam's origin.

You may be required to use the Misc Values box.

Your post may also prompt for tool gauge lengths.


The nature of the additional information required depends largely on your machine's configuration. Contact the developer of your post processor for details

STEP 1: SELECT THE GEOMETRY FILE

Resources - Download the file from <https://www.emastercam.com/trainingfiles/>.

File

- ◆ **Open.**
- ◆ Select "TUTORIAL 4.MCAM" from the directory you saved the file in.
- ◆ Press **Alt + F1** to fit the drawing to the screen.



STEP 2: SELECT THE MACHINE AND SET UP THE STOCK


In Mastercam, you select a **Machine Definition** before creating any toolpaths. The **Machine Definition** is a model of your machine tool's capabilities and features and acts like a template for setting up machining jobs. The machine definition ties together three main components: the schematic model of your machine tool's components, the control definition that models your control unit's capabilities, and the post processor that will generate the required machine code (G-code). For the purpose of this tutorial, we will be using the **Mill Default** machine.

2.1 Open the Toolpaths Manager

*Note: If the **Toolpaths Manager** is not open, follow the instructions provided in **Tutorial 1** on **page 37**.*

2.2 Select the Machine Type

- ◆ From the **Machine Type Group**, select the drop down arrow below **Mill**.
- ◆ Select the **Default**.




*Note: Once you select the **Default**, the **Ribbon bar** changes to reflect the toolpaths that could be used with **Mill Default**.*


2.3 Make Level 10 Visible

View


- ◆ In the **Managers** group, make sure that **Toolpaths**, **Solids**, **Planes**, and **Levels** are selected as shown.



- ◆ From the lower left corner below the **Toolpaths Manager** select the **Levels** tab as shown.




- ◆ Click in the **Visible** column next to **Number 10** as shown.




Num...	Visible	Name	Entities	Level Set
1	X	Geometry	39	
10	X	stock	12	

2.4 Set the Tool Parameters in the Tool Settings page


- ◆ Select the plus sign in front of **Properties** in the **Toolpaths Manager** to expand the **Toolpaths Group Properties** as shown.



- ◆ Select **Tool settings** to set the tool parameters as shown.



- ◆ Change the parameters to match the image below.



Default program number is used to enter a number if your machine requires a number for a program name.


Assign tool numbers sequentially allows you to overwrite the tool number from the library with the next available tool number (First operation tool number 1; Second operation tool number 2, etc.).

Warn of duplicate tool numbers allows you to get a warning if you enter two tools with the same number.


Override defaults with modal values enables the system to keep the values that you enter.

2.5 Set the Stock Shape and Size


- ◆ Select the **Stock Setup** tab to define the stock.
- ◆ In the **Shape** area, enable **Solid/Mesh** and click on the **Select** button as shown.



- ◆ Select the solid from the graphics window as shown.



- ◆ The **Stock Setup** page should look as shown below.




- ◆ Select the **OK** button to exit the **Machine Group Properties** dialog box.



2.6 Make Level 10 Invisible


- ◆ Select the **Levels** tab.



- ◆ Click in the **Visible** column next to **Number 10** to remove the **X** as shown.

Num...	Visible	Name	Entities	Level Set
✓ 1	X	Geometry	39	
10		stock	12	


- ◆ Select the **Toolpaths** tab.



STEP 3: ROTARY 4-AXIS WITH ROTARY CUT

Rotary toolpaths are used on machines that allow simultaneous 4-Axis movements to create a 4-Axis surface machining toolpath which cuts around or along the axis of rotation of the machine (the **X axis** in our case). The **Rotary** toolpath is a finish toolpath. To demonstrate both rotary cut and axial cut, we are going to finish the part first using the rotary cutting method and then the axial cutting method.


Toolpath Preview:




3.1 Machine the Right Side Cam using the Rotary Cut Method

Toolpaths

- ◆ From the **Multiaxis** group, select the **Expand Gallery** icon as shown.




- ◆ From the **Application** group, select the **Rotary** icon.



3.2 Toolpath Type

The **Toolpath Type** page allows you to establish the type of Multiaxis toolpath to create. Toolpath type controls the options available as you proceed down the tree structure. The options are based on the toolpath family selected using the calculation based on buttons, as well as by selecting the picture of the toolpath you wish to create.

- ◆ In the **Toolpath Type** page, the **Rotary** icon should be already selected as shown.




3.3 Set the Tool page parameters

The **Tool** page allows you to select a tool, set the feeds and speeds, enter a comment about the operation, and set other general toolpath parameters.


- ◆ From the **Tree View list**, select the **Tool** page.
- ◆ To select the tool, click on the **Select library tool** button as shown.



- ◆ Select the **Filter** button as shown.




- ◆ Select the **None** button to unselect any previous tool selection as shown.
- ◆ Select the **Ball Endmill** in the **Tool Types** list.
- ◆ Select the drop down arrow in the **Tool Diameter** field and select **Equal**.
- ◆ Enter **1.0** in the **Tool Diameter** value box as shown.




- ◆ Select the **OK** button to exit the **Tool List Filter** dialog box.



- ◆ Select the **OK** button to exit from the **Tool Selection** dialog box. 

Note: The feeds and spindle speed are based on the tool definition. You can overwrite them with the feeds and speed that you want to use. You can also let Mastercam calculate the feeds and speed using the Feed speed calculator.

- ◆ Add a comment in the **Comment** area to identify the toolpath in the **Toolpaths Manager** and also in the **NC** file.
- ◆ The **Tool** page should look as shown.



#	Ass...	Tool Name	Holder N...
1	--	1 INCH BALL ENDMILL	--

Right-click for options

Select library tool... ☐ Filter Active Filter...

☐ To batch

Tool diameter: 1.0
Corner radius: 0.5

Tool name: 1 INCH BALL ENDMILL

Tool #: 1 Length offset: 1
Head #: 0 Diameter offset: 1

Spindle direction: CW

Feed rate: 6.4176 Spindle speed: 534
FPT: 0.003 SFM: 139.7906


Plunge rate: 6.4176 Retract rate: 6.4176
☐ Force tool change ☒ Rapid Retract

Comment
Finish the right side cam using Rotary toolpath with the Rotary cut method

3.4 Set the Cut Pattern Parameters



The **Cut Pattern** settings determine the geometry that the tool follows and how it travels along that geometry. The **Rotary cut** method is designed to cut around the diameter using 4-Axis output.

- ◆ From the **Cut Pattern** page, click on the **Select** button  to return to the graphics view and select the surface.
- ◆ [Select Solid Face or Surface]: Select the right side cam surface as shown.




- ◆ Press **Enter** to finish the selection



- ◆ Enable **Rotary cut**.
- ◆ **Stock to leave on drive surfaces = 0.005**.
- ◆ **Cut tolerance = 0.001**.
- ◆ Enable **Climb** and **One way** as shown.



Surface (1)  

Cut control

Cutting method ☒ Rotary cut ☐ Axial cut

Compensation type Computer 

Compensation direction Left  

Tip compensation Tip  

Stock to leave on drive surfaces 0.005


Cut tolerance 0.001

☐ Reverse cut direction

Diameter (for simulation) 0.25

Direction of closed contours ☒ Climb ☐ Conventional

Direction of open contours ☒ One way ☐ Zigzag



3.5 Set the Tool Axis Control parameters

Tool Axis Control settings determine the tool's orientation in relation to the geometry being cut.

Use center point allows you to generate tool vectors that terminate at the selected point. Deselect it to generate tool vectors that are normal to the surface.


Axis dampening determines the angular change between the vectors. A longer axis dampening length creates less angular change between the vectors. A shorter length provides more tool positions and a toolpath that adheres closely to the surface.

Lead/lag angle (positive/negative value) tilts the tool forward/backward in the direction of the toolpath.

Maximum step controls the distance between passes. The distance is measured parallel to the axis of rotation.

Tool vector length controls the toolpath display by determining the length of the tool axis at each tool position. The recommended value is 1.0".

- ◆ Select the **Tool Axis Control** page and make the changes as shown.



3.6 Set the Linking Parameters

Linking parameters determine how the tool moves when it is not cutting material. In this page you can set the **Clearance**, **Retract**, and **Feed plane** heights and force the tool to move directly between the passes at the feed rate.

- ◆ Select the **Linking Parameters** page and make the following changes as shown.




- ◆ Select the **OK** button to exit the **Multiaxis Toolpath - Rotary** dialog box. 


3.7 Backplot the Toolpath

Backplotting shows the path the tools take to cut the part. This display lets you spot errors in the program before you machine the part. As you backplot toolpaths, Mastercam displays additional information such as the X, Y, and Z coordinates, the path length, the minimum and maximum coordinates, and the cycle time. It also shows any collisions between the workpiece and the tool.


- ◆ In the **Toolpaths Manager**, make sure that the toolpath is selected (signified by the green check mark on the folder icon).
- ◆ Select the **Backplot selected operations** icon.



- ◆ Select the **Play** button to run **Backplot**.
- ◆ Click on the **Options** button.





- ◆ In the **Backplot Options** dialog box, enable **Display vectors** and set the **Length** to **0.25**.





- ◆ Select the **OK** button to exit the **Backplot Options** dialog box.




- ◆ Select the **Play** button to run **Backplot**. 
- ◆ The toolpath should look as shown.




- ◆ Right mouse click and change the **Graphics view** to **Right** as shown.




- ◆ Backplot the toolpath again as shown.




Note: The tool axis orientation due to the 10 degrees lead angle.

- ◆ Select the **OK** button to exit the **Backplot**. 
- ◆ Press **Alt + T** to remove the toolpath display from the graphics window.
- ◆ Right mouse click in the graphics window and select the **Isometric** view as shown.




3.8 Machine the Left Side Cam using the Rotary Cut Method


- ◆ Right mouse click in the **Toolpaths Manager** and select **Copy** as shown.



- ◆ Right mouse click again in the **Toolpaths Manager** and select **Paste** to duplicate the existing toolpath as shown.



- ◆ From the **Toolpaths Manager**, select the **Parameters** in the second toolpath as shown.



www.eMastercam.com

Sitewide Subscription

An eMastercam sitewide subscription will grant you instant access to all of our online resources, including our full library of eBooks and eCourses. Once subscribed, you will be able to watch all of our streaming eCourses in your browser or read any of our Mastercam eBooks using our Webviewer.

[www.eMastercam.com/
sitewide-subscription](http://www.eMastercam.com/sitewide-subscription)



Decades of experience. Thousands of post processors.

Choose In-House Solutions for all your post needs.



Implementing successful post processors for decades, the post department at In-House Solutions has earned a reputation for quality, resulting in one of the largest post departments in the world. We have an extensive library built using our new post engine, "IKE". We are continually developing and expanding our product to include new machines and controllers everyday, and if a post is not already available, we will develop a custom one for nearly any machine. We have great relationships with OEMs who provide technical information for both machines and controls, which in turn allows us to produce post processors that will generate edit-free code and run your machine efficiently.

Be sure to ask your Mastercam reseller for an In-House Solutions IKE post!

www.inhousesolutions.com/posts





*Included with each eCourse:
HLE demo software,
corresponding PDF eBook,
and personalized
final certificate.*

LOGIN & LEARN!




Mastercam eCourses provide both novice and seasoned Mastercam users with the tools and information they need to excel.

Approximate completion time ranges from 7.5 to 15 hours depending on the eCourse, making it possible for employees or students to gain new skills outside of work or studies.

- Online previews with table of contents including the time it takes to complete each session.
- Mastercam 2020 Home Learning Edition Demo Software download is included so you can follow along with our instructors.
- Corresponding eBook is provided.
- Quizzes follow each tutorial.
- Personalized certificate of completion for each successfully completed eCourse.
- **Instant, lifetime access**

www.eMastercam.com/eCourses



OCTOPUZ®

Robot Programming & Simulation Software

Program and generate robot code in a simple and easy way, regardless of application and brand. Spend less time programming and more time manufacturing!

Why choose OCTOPUZ?

- Multiple robots? No problem!
- Most robot brands supported
- Simple simulation building
- Extensive component library

- Automatic toolpath solving
- Application versatility
- CAM interface
- Complex kinematic systems

www.OCTOPUZ.com



TELL US WHAT YOU THINK

Our goal is to provide you the best Mastercam Training Solutions,
and we do that with your help.

Tell us what you like about our training solutions.

Let us know what you think can be improved.

Give us suggestions for future products.

www.eMastercam.com/feedback

We appreciate your feedback!

eMastercam.com
YOUR ONLINE MASTERCAM SOURCE



**DID YOU
LIKE THIS
BOOK?**

Training Tutorials
Instructor Materials
Handbooks
Professional Courseware
Pro. Certification Curriculum
Online Video eCourses
Site Licenses
Sitewide Subscription
Online Community

Discover other Mastercam Training Solutions at
www.eMastercam.com